



AGENDA

Military Munitions Response Program (MMRP)
Army National Guard (ARNG) MMRP Sites
Fort Indiantown Gap MMRP Inventory and Site
Inspection



DoD's

Military Munitions Response Program


Established by:


- 2001 Defense Environmental Restoration Program (DERP) Guidance (10 U.S.C. 2701).
- FY02 National Defense Authorization Act. Sections 311 & 312 (10 U.S.C 2710).

Requires:

- Inventory of non-operational Defense Sites, known or suspected to have Unexploded Ordnance (UXO), Discarded Military Munitions (DMM) or munitions constituents.
- Implementation of appropriate Response Actions to reduce risk to human health and the environment.

Army National Guard Military Munitions Response Program Active Sites





ARNG ENVIRONMENTAL PROGRAMS







FORT INDIANTOWN GAP MMRP Inventory and Site Inspection

- 2003 Closed, Transferred, and Transferring (CTT)
 Range/Site Inventory Report.
 - Artillery Ricochet Area 1995 US Army Safety Regulation 385-1 for FIG: Restricted Airspace R5802A "fall area for spent ordnance ricocheting north of Second Mountain".
 - Cold Springs Range Fan Artillery Firing Point 1940-1970.
- 2007 Historical Record Review.
 - Ricochet Area MRS Combined 2 sites. Eliminated area northwest of Stony Mountain.
- 2009 Site Inspection Report

ARNG ENVIRONMENTAL PROGRAMS







1956 Hummelstown Quadrangle Map With FIG Range Overlay



FORT INDIANTOWN GAP MMRP Inventory and Site Inspection

- 2003 Closed, Transferred, and Transferring (CTT)
 Range/Site Inventory Report.
 - Artillery Ricochet Area 1995 US Army Safety Regulation 385-1 for FIG: Restricted Airspace R5802A "fall area for spent ordnance ricocheting north of Second Mountain".
 - Cold Springs Range Fan Artillery Firing Point 1940-1970.
- 2007 Historical Record Review.
 - Ricochet Area MRS Combined 2 sites. Eliminated area northwest of Stony Mountain.
- 2009 Site Inspection Report.

ARNG ENVIRONMENTAL PROGRAMS

